

SUBJECT PROPERTY INFORM	FILE #:	2005691	
Address: 1234 Elm Street	City: Pleasantville	State: MN	Zip: 55812
Structure Age(yrs.): 25	Inspection Date: 06/25/00		
Structure Style: Two-story	Weather: Sunny	Temperature: +	76° F
Limiting Conditions: Snow Cover	☐ Ice ☐ Rain ☐ Otho	er:	

5731 SHETLAND DRIVE NW - ROCHESTER, MN 55901 - (507)288-2622







Date: 06/25/00

CLIENT INFORMATION FILE #: 2005691								
Name: Mr. &	Mrs. Home Buyer	Phone #:	(123)456-7890	Email:				
Address: 5555	5 Old Home Street	City: We	stmont	State:	VA	Zip:	01222	
Buyers Agent:	Buyers Agent	Company:	Buyers Agent's Re	al Estate (Co.			
Listing Agent:	Listing Agent	Company:	Listing Agent's Re	al Estate	Co.			

REAL ESTATE DISCLOSURE STATEMENT	Disclosure Date: 06/01/00
I declare to the best of my knowledge the following information	on to be true and complete:
1. Foundation problemYes ☐ No ☒	5. Drain tile problemsYes No 🖂
2. FloodingYes No	6. Cracked floors/wallsYes ☐ No ☒
3. Wet floor/walls Yes ⊠ No □	7. Sewer backupYes No
4. Leakage/seepage	8. Other
THE ABOVE INFORMATION IS TAKEN DIRECTLY FRO	OM THE SELLER'S DISCLOSURE STATEMENT AND
IS MADE A PART OF THE INSPECTION REPORT GIVEN	N BY DSP.

IMPORTANT HEALTH AND SAFETY INFORMATION - Any house built before 1978 may have lead-based paint. The presence of lead-based paint can be a health hazard. For more information on how to protect yourself and your family from this and other environmental hazards, please call your local Health Department.

AGREEMENT, SCOPE, GENERAL LÍMÍTATIONS AND EXCLUSIONS

THIS AGREEMENT is made between DSP, inc., referred to as "Inspector", and the undersigned, referred to as "Client".

- 1. This Report is not a code compliance inspection and will not be used by the Department of Inspections as a basis for enforcing Local Ordinances.
- 2. This Report offers a visual inspection of the accessible areas of the items included for inspection, to determine if, at the time of inspection, said items were performing their intended function, without regard to life expectancy.
- 3. The purpose of the inspection is to identify visual defects and/or conditions that, in the judgment of the Inspector, adversely affect the function and integrity of the items, components, and systems inspected, or the health and safety of the occupant(s).
- 4. Inspections are basically visual, and rely upon the opinion, judgment, and experience of the inspector, and are not intended to be technically or mechanically exhaustive. The determination of conditions that may have occurred previous to the inspection and may be hidden or not readily visible during the inspection are excluded.
- 5. Inspections performed are neither an expressed or implied warranty or guarantee of the adequacy, performance, or useful life of any item, component, or system that is in, on, or about the inspected property.
- 6. Detached building(s) located on the property will be inspected only when that building is specifically listed in the Report.
- 7. The Inspector is not responsible for the determination of the presence of dirt, dust, and other conditions which might provide harborage or sustenance for bacteria, molds or fungi, which could cause reaction in certain individuals or animals; the presence of air-borne particles (such as asbestos), noxious gases (such as radon), toxic, carcinogenic, or malodorous substances, or other conditions which may cause the above; underground storage tanks; water wells; septic systems; central vacuum systems; telephone; CATV; intercom; water softener; household appliances; security and fire protection systems; paint, wallpaper, and other interior treatments; governing codes, ordinances, statutes, and covenants. Any comments about the aforementioned items are informal only and DO NOT represent an inspection of the items.
- 8. The determination of the presence of, or damage caused by termites or any other wood-damaging insects or organisms is excluded.
- 9. The Inspection and Report are opinions only, based upon the visual observation of existing conditions only, at the time of inspection. THIS REPORT IS NOT INTENDED TO BE, NOR IS IT TO BE CONSTRUED AS, A GUARANTEE OR WARRANTY, NOR AS ANY FORM OF INSURANCE EXPRESSED OR IMPLIED. The Inspector will not be responsible for any repairs or replacements with regard to this property or the contents thereof.
- 10. This Agreement represents the entire agreement between the parties. If a dispute arises out of or relates to this contract, or the breach thereof, and if said dispute cannot be settled through direct discussions, the Inspector will be held liable for the cost of the inspection only.
- 11. The Inspector is not required to determine property boundary lines or encroachments, easements, or right-of-ways.

I have read the above information, and agree to allow an inspection of the above property, and to be bound by all agreements and understandings as set forth herein.

Signature of Client:	Mr. & Mrs. Home Buyer	Date:	06/25/00
C			



Date: 06/25/00

OUR GOALS AND STANDARDS

It is our goal to identify potentially significant expenses that would affect a typical purchaser's buying decision. We will always strive to add significantly to your knowledge of the building or structure, within the scope of the inspection. We will not tell you everything about the property or structure, but our report will put you in a much better position to make an informed decision.

It is important to realize that emphasis is placed on major expenses, typically health or safety issues, and mechanical or structural inadequacies. While some of the less important deficiencies are addressed, an all inclusive list of minor building flaws is not provided.

The inspection is performed in accordance with normal standards of practice. This is not a Building Code or By-Law compliance inspection.

No comment is offered on any environmental concerns including such things as urea formaldehyde foam insulation, asbestos, radon gas, lead paint, or buried fuel tanks. We will, however, recommend when and if we believe an outside specialist should be consulted.

The report is a professional opinion based on a visual inspection of the accessible features of the building. Without dismantling the house or its systems, there are limitations to such an inspection. Throughout any inspection, references are often drawn which cannot be confirmed by direct observation. Therefore, it should be understood that we can reduce the risk of purchasing; however, we cannot eliminate it, nor do we assume it.

We are not associated with any seller, contractor, lawyer, or Realtor. Other than the inspection fee, we have no anticipated financial interest in the property. The report will not be released to anyone without your permission.

UNFORESEEN REPAIRS

Each house has many identical components (electrical outlets, windows, bricks, etc.). We will inspect a representative sample of these. This means that some deficiencies which were detectable may go un-noted. We ask that you understand and accept this. As a result of these items and other items which are impossible to anticipate, we suggest a budget figure of roughly one percent (1%) of the value of the home be set aside every year for unforeseen repairs. In some years the expenditures will be less, in others more, but we have found this to be a good average figure.

If you receive opinions which differ from anything in this report, please contact us before committing to any expense.



Date: 06/25/00

TABLE OF CONTENTS

		<u>Section</u>	Page Number
	COVI	ER SHEET	1
	INFO	RMATIONAL	2-3
	TABL	LE OF CONTENTS	4-6
1.0	STRU	CTURAL / BASEMENT	7
	1.1	Basement Stairs/Landing	7
	1.2	Basement Floor	7
	1.3	Basement Foundation Walls	7
	1.4	Floor System/Columns & Beams.	7
	1.5	Crawl Space. Remarks.	7
	1.6	Remarks	7
	1.7	Basement Dampness	7
	1.8	Basement Sleeping/Other Rooms.	7
	1.9	Floor Drains	7
	1.10	Remarks.	7
2.0	PLUN	MBING / BATHROOMS	8
	2.1	Waste And Vent Piping	8
	2.2	Water Piping.	8
	2.3	Main Water Line.	8
	2.4	Gas Piping.	8
	2.5	Water Heater.	8
	2.6	Remarks	8
	2.7	Bathrooms.	8
	2.8	Remarks	8
3.0	HEAT	FING / COOLING	9
3.0	3.1	Heating System.	9
	3.1	Distribution	9
	3.3	Humidifier	9
	3.4	Supplementary Heat	9
	3.4	Remarks	9
	3.5 3.6	Cooling System.	9
	3.0 2.7	Domostro	9



Specialists"

GENERAL HOME INSPECTION FIELD REPORT



		<u>Section</u>	Page Number
4.0	ELECTRICA	AL / KITCHEN	10
	4.1 Electr	rical Service	10
	4.2 Outle	ts/Fixtures/Switches	10
	4.3 Rema	rks	10
	4.4 Appli	ances	10
	4.5 Pluml	bing Fixtures	10
		rks	10
5.0	GENERAL I	INTERIOR / ATTIC	11
	5.1 Major	· Wall/Ceiling Finishes	11
	5.2 Major	Floor Finishes	11
	5.3 Wind	ows/Doors	11
	5.4 Heat/	Cooling Source	11
		rks	11
	5.6 Roof	Decking And Rafters	11
		Ventilation	11
		Insulation	11
		rks	11
6.0	EXTERIOR	/ ROOF	12
	6.1 Exter	ior Structure Walls	12
		Windows (frames/storms/screens)	12
		a/Gutters/Downspouts/Misc	12
		hed Decks	12
	6.5 Rema	rks	12
	6.6 Roof	Covering/Flashing,	12
	6.7 Chim	ney	12
	6.8 Rema	rks	12
7.0	GROUNDS	GARAGE	13
,		nage	13
		ks/Driveways/Patios/Steps	13
		ining Walls	13
		tric Outlets/Fixtures.	13
		arks	13
		e Of Garage	13
		f Structure And Covering.	13
		Structure And Covering.	13
		r	13
		rs	13
		tric Outlets/Fixtures.	13
		arks	13
	1.12 N CIII	ai NS	13
8.0		N SUMMARY	14
9.0	ADDENDUN	A SECTIONS (if any)	15





Your On-Line Home Inspection Resource

How To Read The Inspection Report:

The major categories will be graded using the following:

S = Satisfactory


N = Needs Repair

U = Unsatisfactory

 $\mathbf{H} = Hazardous$

 $\mathbf{C} = Comments$

Items marked with a asterisk may require further attention and(or) repair. Follow up here may be needed.





The Information symbol denotes areas of special information pertaining to the section. This symbol may also be followed by the words LIMITATIONS -OT- REFERENCE, which serve to define the type of special information being given.



The camera symbol indicates that a photograph of the of the area being described is available on page 15.

Your name and file number will appear here

"S" = Satisfactory Page #: 6 of 15 "U" = Unsatisfactory

"H" = Hazardous

"C" = Comments

"N" ▼Needs Repair

(* Signifies items that warrant attention/repair)
© 1997-2000 DSP,inc. All Rights Reserved

Client Name: Home Buyer File Number: 2005691





"The Home Inspection Specialists"

SEC	CTION 1.0	STRU	CT	URAL
NFORMATION LIMITATIONS	Restricted/No Access To:	Finishes and/or Storag	ge Cor ent ut eport,	
1.1	BASEMENT STAIRS/LANDIN	IG	S	☐ Do not meet rise/run/width requirements* ☐ Missing/Unsafe handrails* ☐ In need of repair* ☐ Other:
1.2	BASEMENT FLOOR Type of construction: <i>Concrete</i> ;		C	☐ Cracking, heaving, buckling ☐ Improper slope ☐ Unable to fully view/covered by finishes ☐ Other: - Typical floor cracking notedcracks should be filled / caulked.
1.3	BASEMENT FOUNDATION V Type of construction: <i>Block</i> ; Configuration: <i>Full Basement</i>	VALLS	S	☐ Visible cracking/bowing* ☐ Further evaluation ☐ Unable to fully view/covered by finishes ☐ Other:
1.4	FLOOR SYSTEM/COLUMNS Floor Joist Type: 2 x 10 dimensi Floor Decking Type: Oriented-str	onal lumber ;	S	Notching/alterations* Dry rot* Sagging* Other:
1.5	CRAWL SPACE			☐ Present ☐ Not present ☐ Not accessible* Dampness: ☐ None ☐ Some signs* ☐ Extensive*
		P.A.	S In	MENT Comments
1.7 REFERENCE 1.8	BASEMENT DAMPNESS Many factors can combine to co (e.g. lack of proper exterior grainstallation, settled exterior sury wet basements cannot be assessed and inconvenience factor during may not be clues that may indice BASEMENT SLEEPING/OTH	ntribute to a wet basement ding, poor gutter & downs, faces, etc.). Unfortunately, ed for their severity, freque to a one-time visit. There ma ate basement dampness.	pout ncy,	 ☐ Current/active leakage* ☐ No dampness visible ☐ Past staining/leakage/mildew* ☐ Rust on nails* ☐ On basement walls/floors/paneling/drywall/etc.* ☐ Other: - There was evidence of past water leakage / mold on the walls along the N & E walls. Please refer to the Remarks section below, for further comments: ☐ Sump basket ☐ Sump pump ☐ Beaver system ☐ "Do-it-yourself" modifications made to heating, electrical, structural, or finish work* - The two bedrooms along the S end of the basement have been finished off in a "do-it-yourself" manner, i.e. insufficient heat supply ducts, several outlets not properly wired (see Section #4.2). It is recommended that professional repairs
See Se	ections #6.3 and #7.1 for referenc ump pump is discharging into the	е.		be made here. Tested Not tested as likely contributors to the basement leakage noted. iolation of City Ordinance #2776. Recommend re-directing





"The Home Inspection Specialists"

SEC	TION 2.0 PL	UM	BING
INFORMATION REFERENCE	Bathrooms are typically subjected to more moisture than ot kept in mind: It is important to limit the amount of moisture exhaust fans & maintenance of the caulking & grouting of continuous transmitted.	her roo e/water ceramic GFCI	oms in the house. Because of this fact, several things should be intrusion into the surrounding walls, ceilings, etc. by use of c tiled surfaces. Bathrooms should also be equipped with GFCI 's or exhaust fans; upgrading in these areas is recommended.
2.1	WASTE AND VENT PIPING (lower level)	N	Makeshift repairs*
	Apparent Waste Type: Public Private Private		Leaks: None observed Some signs* Note the sign of the sign o
2.2	Waste Line Type: PVC; WATER PIPING	S	- No trap on laundry sink waste line recommend adding. Water was: ON □ OFF at the time of inspection
INFORMATION LIMITATIONS	 ∑ Water Treatment Equipment Not Inspected ∑ Concealed Plumbing Not Inspected ☐ Hot Tubs/Spas & Other Specialty Systems Not Tested ☐ Isolating/Relief Valves & Main Water Line Shut-Off Valve Not Tested 	2	Leaks: None observed Some signs*
	Apparent Water Supply Type: Public ☑ Private ☐ Water Line Type: Copper;		
2.3	MAIN WATER LINE Type of water line material: Copper Main shut-off valve location: Basement	S	Leakage at main shut-off valve* Other:
2.4	GAS PIPING	S	Unused lines not capped* No shut-offs at appliances*
2.5	WATER HEATER Make: 1) <i>MorFlo</i> 2) Model: 1) <i>GVF84336</i> 2) Output (b.t.u./hr.) : 1) <i>33,000</i> 2) Capacity (US gals.) : 1) <i>40 gallons</i> 2)	S	No relief valve* No downspout* Poor venting* Rust/leakage* Type of fuel: Natural gas; The water heater is newer (approx. 5 years old), and operated well.
2.6	REMARKS:		
	BAT	HR	COMS Comments
2.7	BATHROOMS Lower level Bath exhaust fan No exhaust Main level Bath exhaust fan Upper level Bath exhaust fan Recommend installing an exhaust fan in the lower level bas an upgrade.	•	Leaks: None observed
2.8	REMARKS:		





"The Home Inspection Specialists"

SEC	TION 3.0	HE	AT	ING
INFORMATION REFERENCE LIMITATIONS	Any combusting appliant be tested at least once a detector be installed on Radiator Zone Valve	year, by a qualified heating technic every level of your home.	cian.	nonoxide into the home. It is recommended that these appliances It is also recommended that at least one carbon monoxide ot Tested Comments
3.1	HEATING SYSTEM		S	Type of fuel: Natural Gas
	Ur	it 1) <i>American Standard</i> it 2) it 1) <i>TUD080B924A0</i>		Heating plant type: Forced Air ☐ Rust/debris on interior* ☐ Needs cleaning*
		iit 2)		Contact a specialist to fully inspect* Unsafe venting*
	Output (Btu/hr): Unit 1)	80,000 Unit 2)		Not visible/enclosed combustion chamber*
	(Note: A digital CO test b	Monoxide Test Results y itself, may not reveal some hidden defea		- The furnace is approx. 10 years old, and operated well at the time of the inspection. The interior was dirty, as was the filter. Recommend cleaning / servicing the unit.
	Supply Air: 0.00 Exhaust Gasses: 9.00			
3.2	DISTRIBUTION	ppin wunn acceptable umi	N	Type of distribution: Ductwork Radiators
				☐ Insufficient supplies and(or) return air vents* - See Section #1.8 for reference to insufficient heat vents.
3.3	HUMIDIFIER Make	e: Aprilaire #550	S	Not present Not functioning* Not tested
3.4	SUPPLEMENTARY H			
	Fireplace/Stove present			<u>Location</u> <u>Type</u>
A		places(flues & firebox) be cleaned a		1) Lower Level; Wood burning fireplace
$\ \mathbf{U}\ $		basis to prevent the buildup of creos	ote,	2);
INFORMATION	which can be a cause of	on, during a visual inspection, to be) 1111-	3) ; - Creosote buildup was noted in the chimney flue, and the
REFERENCE	able to view all areas o	f the flue & firebox due to lack of ac	eess.	damper handle was broken. Repair / cleaning needed.
		entire flue due to lack of access*		Recommend professional cleaning & inspection of flue*
3.5	REMARKS:			
		CC	OOI	LING Comments
3.6	COOLING SYSTEM		S	Air-conditioning present Yes No 🗌
	Note: The outside air t	emperature must be 55-60°F or ab	ove	Viewed in operation Yes ⊠ No □
U		on for a minimum of 24 hours, other		- The compressor operated well. Unit is approx. 5 years old.
INFORMATION		not be operated without possible dan	mage	
REFERENCE	to the compressor. A/C Make: Carrier;			Compressor not operated due to outside temperature*
	Model: 38TG024300			(Please refer to comments at left)
3.7	REMARKS:			





"The Home Inspection Specialists"

SEC	CTION 4.0	ELECTR	CAL	Comments
4.1	ELECTRIC SERVICE	S	_	anel Size (number of circuits)
0	The electrical system is very important from convenience standpoint. Generally speaking are expanded and upgraded over the life of	g, electrical systems a house, rather than	Total Circuits: 17= 24 Apparent service size a	0V(3);120V(14) at panel: AMPS: 150 VOLTS: 120/240
REFERENCE	taken out and replaced on a regular basis. not uncommon to have a house with a comb newer systems present (e.g. wiring, outlets,) Note: For most houses today, a 60 amp set	ination of older and ixtures, etc.).	Type of main service po	anel: ⊠ Breakers □ Fuses
4.2	OUTLETS/FIXTURES/SWITCHES	N	☐ Visible repairs/alte	rations* Reversed polarity*
	- A representative #. of outlets/switches were	e randomly tested.	Professional repairs	
	- Unsafe wiring present in the lower level (s		Knob & tube wiring	
	Contact an electrician to make repairs her	e.	Requires installation	on of GFCI's in potential "wet" areas*
4.3	REMARKS:		1	
	t is recommended that you have at least one s		1	test operation monthy.
1	he battery of the unit in the lower level famil	y room neeas to be	repiacea.	
		,		
		KITCI	EN	
	Kitchen appliances are mechanical devices	and as such, may o	perate one moment and th	en later malfunction. It is therefore
	strongly recommended that all appliances in closing, to determine if they are still operati		cked by you and your Rea	ltor at your final walk-through, before
REFERENCE	crossing, to determine if they are still operation			
LIMITATIONS			Self-Cleaning Feature	
4.4	Effectiveness Of Dishwasher Drying Cyc		Cl d D D	Comments
4.4		Present OK	Clothes Dryer Po	Gas (Natural /Propane)
	Dishwasher Yes	No 🗆	Not viewed	Sus (Natural / Fropunc)
	□ Range Yes 2	= =		
	Oven Yes	_ = =	Appliances not test	
	□ Refrigerator Yes □ Exhaust Vent Yes	= =	_	operation of all your appliances when
	Door Bell Yes		you perjorm your wa	alk through, before closing escrow.
		No 🗵		
	□ Trash Compactor Yes □			
	Other:			
4.5	PLUMBING FIXTURES	S	Poor water flow*	Leakage or seepage*
			☐ Makeshift repairs*	Other:
4.6	REMARKS:			





"The Home Inspection Specialists"

SEC	TION 5.0	GENERAL	INTERIOR
REFERENCE LIMITATIONS	are not always an indication of a major	structural defect. For t s, expansion/contraction ficant changes, and con New Finishes/Paint	s, especially of wood frame structures. Although unsightly, cracks the most part, cracking in plaster and drywall can be attributed to of wood due to moisture, etc. As with any cracking though, it is stact an expert if any are noted. No Comment Made On Cosmetic Finishes View of Windows/Glass Limited by Dust/Screens/Etc. Comments
5.1	MAJOR WALL/CEILING FINISHE	S N	Type of material: Drywall;; □ Typical flaws present □ Large cracks* □ Stains* - A stain was present in the upper level hallway ceiling, under a roof vent in the attic, directly above - tested actively damp. See Section #6.6 for reference.
5.2	MAJOR FLOOR FINISHES Out-of-level floors* Deterioration/soft floors*		☐ Hardwood ☐ Carpet ☐ Vinyl ☐ Tile ☐ Slate/Marble/Etc. ☐ Other:
5.3	WINDOWS/DOORS Window Brand: Andersen; Type of windows Frames:	S Metal	□ Paint and(or) glazing flaking & peeling on frames* □ Difficult/unable to open* □ Rot on frames* □ Cracked/broken glass* □ Poor finish condition* □ Failed thermopane seals* Repairs needed on: □ None □ Some* □ Many* Rear lower level patio door difficult to open / close. Noted excessive amount of dirt / debris in track. Needs cleaning.
5.4	Glazing: Single Double HEAT/COOLING SOURCE	e Triple	Type: Registers Electric Baseboard Space Heater Other:
5.5	REMARKS:	ATT	IC
INFORMATIONS LIMITATIONS	 ☐ Continuity Of Air/Vapor Barrier Not ☐ Walls/Decking/Rafters Spot Checked ☐ Entire Attic Space Was Not Fully Accomponents Were Not Able To Be In Components 	Verified I Only cessible And All	Attic Access/Roof Space Viewed From: ☐ Ladder At Hatch ☐ In The Attic ☐ No Access* Comments
5.6	ROOF DECKING AND RAFTERS - See Section #6.6 for reference.	C	☑ Dampness/staining* ☐ Sagging* ☑ Notching/alterations* ☐ Deteriorated decking*
5.7		Sable S	☐ Obstructions to air flow* ☐ Recommend increasing air flow*
5.8 REFERENCE 5.9	ATTIC INSULATION New house standards call for approximation, which equals an R-Value of colder homes have significantly less than Insufficient attic insulation & ventilation excess energy usage, ice-dam related was REMARKS:	upprox. 40-42. Many this amount present. In can contribute to	Type of insulation: Blown; Approximate insulation thickness (in inches): 16" Recommend increasing amount of insulation* - Note: Additional insulation has been added at some point in the past - meets current new house insulation standards.
3.7	ALL MINIST		





"The Home Inspection Specialists"

SEC	TION 6.0 EXTE	RIOR				
(INFORMATION	The exterior components of a house work together to provide a watertight "shell", if all the parts are doing their job. Many new houses today, are built with low maintenance exteriors (e.g. permanent siding, clad windows & doors, metal soffit & fascia, etc.), which minimize the need for exterior painting. Most houses though, have at least some exterior surfaces that require annual care and maintenance. Surfaces protected with lead-based paint are a potential health hazard. It is recommended that you contact your local Department of Health for more information on how you can protect yourself.					
REFERENCE	☐ Limited Visibility Due To Snow (roof, paved surfaces, groun ☐ Absence Of Historical Clues Due To New Finishes/Paint ☐ Vines/Shrubs/Trees Against Building Restricting View	ds) Restricted/No Access Under Steps/Porches/Decks Comments				
6.1	EXTERIOR STRUCTURE WALLS S	Paint peeling/flaking* Areas of deterioration*				
	Type of siding material: Permanent Vinyl;	☐ Moisture damage* ☐ Caulking needed* ☐ Repairs are needed*				
6.2	DOORS/WINDOWS (frames/storms/screens)	- Missing 2 screens on the front main level living room windows.				
6.3	FASCIAS/GUTTERS/DOWNSPOUTS/MISC.	Type of gutters: ☐ Not present ☐ Vinyl ☐ Metal ☐ Missing gutter extensions* ☐ Need cleaning/repair* Noted 3 downspout extensions missing along N side.				
6.4	ATTACHED DECKS	□ No deck present □ Poor plate connection* □ Makeshift construction* □ Evidence of rotting* □ No flashing at ledger board* □ Other: - Rotted stringers on deck stairs. Professional repairs recommended.				
6.5	REMARKS:					
	RO	OOF Comments				
6.6	ROOF COVERING/FLASHING N	Evidence of:				
INFORMATIONS LIMITATIONS	Roof Inspection Limited/Prevented By: Snow/Ice Wet Height No Access Slope Roof Inspected By: Binoculars Ladder At Edge Walking On Type of roof covering: Composition shingles; Approximate Age of Roof Covering: ± 5 yrs.	☐ Curling* ☐ Cupping* ☐ Cracking* ☐ Moss Buildup* ☐ Gravel Loss* ☐ Leaking* ☐ Missing/Broken Shingles* ☐ Past Repairs* - Noted some pitting and gravel loss on shingles, as well as holes in 2 roof vents. Suspect hail damage. Recommend that the Seller follow up with their insurance company.				
6.7	CHIMNEY Location 1): Fireplace Location 2):	Type of chase construction:				
6.8	REMARKS:					





"The Home Inspection Specialists"

SEC	CTION 7.0	GROUN	DS Comments
7.1 INFORMATION REFERENCE	DRAINAGE Improper exterior grading & drainage is a major water intrusion in basements. As a rule of thumb, away from the foundation walls, for the first 5-8 f recommended. This is a MUST to maintaining a decommended.	, 5-8" of slope feet, is	Low areas are present along the: North* South* East* West* Noted soil settlement along the N & E sides. Recommend re-grading for better drainage "away" from the house. Recommend additional lot grading: Yes No
7.2 INFORMATION REFERENCE	WALKS/DRIVEWAYS/PATIOS/STEPS Settled concrete can pitch towards the house, force flow against the foundation walls. This can creat water problems as well as place undue stress on twalls. Areas such as this should either be mud-jatheir original height, or replaced. Type of materials used:	te basement he foundation	 Settled/cracked sections* ☐ Trip hazards present* Caulking needed between joints* Mud-jacking or replacement recommended*
7.3	- Driveway: Concrete; - Sidewalks: Concrete; - Patios: None; RETAINING WALLS	8	Bowing/tipping/rotting* Repairs needed*
7.4	Type of materials used: Wood; ELECTRIC OUTLETS/FIXTURES	S	Location of electrical primary service: Underground
7.5	REMARKS:		No weather tight covers on exterior outlets*
0	section does not apply to any out-buildings (e.g. s	ing structure tha sheds, barns, etc.	RAGE t is on the same grounds as the main house structure. This), unless specifically identified. Many of the exterior finishes
REFERENCE	on a garage will be of similar design and constru	enon as the matr	Comments
7.6	TYPE OF GARAGE		
7.7	ROOF STRUCTURE AND COVERING	S	Same as house Other:
7.8	WALL STRUCTURE AND COVERING Type of wall covering/finish: Unfinished;	S	☐ Deteriorated sill plates* ☐ Damaged/No firewall* ☐ Leakage stains* ☐ Other:
7.9	FLOOR Type of material: ☐ Concrete ☐ Gravel ☐ Asphalt ☐ Other	S	☐ Typical Cracking ☐ Large Cracks/Settlement*
7.10	DOORS Electric opener: □ Present □ Not present □	S	Safety auto-reverse: ☐ Operable
7.11	ELECTRIC OUTLETS/FIXTURES	S	☐ Electricity Not Present ☐ Do-It-Yourself Repairs* ☐ Unsafe wiring* ☐ Repairs Recommended*
7.12	REMARKS:		





"The Home Inspection Specialists"

Your On-Line Home Inspection Resource

CTION 8.0 **INSPECTION SUMMARY**

MAJOR REPAIR - REPLACEMENT ITEMS

The following are items that have failed, and(or) have the potential to pose a significant expense over the near term.

SECTION	Note: Please refer to the attached Repair Price Guide (located on the inside back cover), for approximat to repair & replace many of the more common components found in a typical home.	
	REMARKS	Cost
	There were some items in need of attention, as per below. Please refer to the text of the Inspection Report for further details.	
1.	<u>Basement Leakage</u> — While no active leakage was present at the time of the inspection, poor exterior landscaping & missing gutter extensions are certainly contributors to the past leakage noted. It is recommended that the N & E sides be re-graded & the missing extensions replaced.	400 – 650
2.	<u>Do-It-Yourself Basement Finishing</u> – Recommend installing heat vents in the lower level rooms, and professional repair of the electrical wiring here. Contact professionals for repair estimates.	200 - 350
3.	<u>Sump Pump</u> – It is recommended that the sump pump discharge be re-directed so that flow is to the outside. Contact a plumber for an estimate.	175 - 250
4.	<u>Ceramic Tile</u> – Contact a ceramic tile specialist for estimates to repair / replace the tile in the master shower.	1,200 – 1,600
5.	<u>Deck Stairs</u> – The deck stairway stringers are rotted and unsafe for use. Contact a contractor for repair estimates here.	200 - 300
6.	Roof Vents / Shingles – Hail damage noted on shingles and roof vents. Recommend that the Seller follow up with his insurance company.	- ? -

Be sure to refer to the Home Maintenance Checklist located on the inside front cover, for a helpful summary that details some of the more common areas needing attention around a typical home.

Inspector:

NOTE: THE ENTIRE REPORT SHOULD BE READ AND TAKEN INTO ACCOUNT, INCLUDING ALL COMMENTS, RECOMMENDATIONS, AND REMARKS, TO GAIN A PROPER PERSPECTIVE OF THE CONDITION OF THE SUBJECT STRUCTURE. The above list itemizes certain repair or replacement considerations noted during the inspection of the subject structure. The items included are of a health or safety, structural, or mechanical concern. This list is not intended to be all inclusive, and costs are approximations only. All items considered should be verified by estimates from reputable contractors. THIS ESTIMATE IS NOT INTENDED TO BE, NOR IS TO BE CONSTRUED AS, A GUARANTEE OF ACTUAL REPLACEMENT OR REPAIR COSTS.

© 1997 - 2000 DSP,inc. All Rights Reserved

"S" = Satisfactory "C" = Comments "U" = Unsatisfactory "H" = Hazardous Page #: 14 of 15 (* Signifies items that warrant attention/repair)

"N" = Needs Repair **Client Name: Home Buyer File Number: 2005691**





Your On-Line Home Inspection Resource

SECTION 9.0 ADDENDUM SECTIONS

The following section contains items such as photos, additional reports, specialty inspections, etc. that provide additional information and reference to the Inspection Report.



Damaged ceramic tile in master shower.



Rotted deck stairway stringers.



Hail damage on roof vents.

File Number: 2005691